



DEFENSE INFORMATION SYSTEMS AGENCY

P. O. BOX 549
FORT MEADE, MARYLAND 20755-0549

IN REPLY
REFER TO: Joint Interoperability Test Command (JITE)

4 Apr 12

MEMORANDUM FOR DISTRIBUTION

SUBJECT: Extension of the Special Interoperability Test Certification of the Avaya CS2100 XA-Core SE09.1 –Aura™ AS5300 Version 2.0 Multifunction Softswitch (MFSS) (with specified patch releases) from Patch Bundle 18 to Patch Bundle 23

References: (a) DoD Directive 4630.05, “Interoperability and Supportability of Information Technology (IT) and National Security Systems (NSS),” 5 May 2004
(b) CJCSI 6212.01E, “Interoperability and Supportability of Information Technology and National Security Systems,” 15 December 2008
(c) through (f), see Enclosure

1. References (a) and (b) establish the Joint Interoperability Test Command (JITC), as the responsible organization for interoperability test certification.

2. The Avaya CS2100 XA-Core SE09.1 - Aura™ AS5300 Version 2.0 MFSS (with specified patch releases), hereinafter referred to as the System Under Test (SUT) was originally certified as a MFSS (TN 0903501), Reference (c). The vendor submitted a Desktop Review (DTR) to update the SUT software from Patch Bundle 18 to Patch Bundle 23 to resolve interoperability issues that were identified in the operational environment. Patch Bundle 23 is a rollup of all the fixes in Patch Bundles 19, 20, 21, 22, and 23. JITC conducted testing using product requirements derived from the Unified Capabilities Requirements (UCR), Reference (d) and test procedures, Reference (e). The SUT’s certification status will be evaluated during operational deployment. Any new discrepancy noted in the operational environment will be evaluated for impact on the existing certification. These discrepancies will be adjudicated to the satisfaction of Defense Information Systems Agency (DISA) via a vendor Plan of Action & Milestones (PoAM), which will address all new critical Test Discrepancy Reports (TDRs) within 120 days of identification. JITC does not certify any other configurations, features, or functions, except those cited in this memorandum, or authorized by the Program Management Office. This certification expires upon changes that affect interoperability, but no later than three years from 1 September 2010, which is the date the SUT was posted on the Unified Capabilities (UC) Approved Products List (APL).

3. JITC approves the extension of this certification for DTR 18 submitted to add Patch Bundle 23. All the interoperability fixes in Patch Bundle 23 were regression tested by JITC, Fort Huachuca, Arizona, from 8 through 23 March 2012. There were no new Information Assurance (IA) findings during the regression test and therefore the original IA approval applies to this DTR. There was one interoperability discrepancy found during regression testing. An unattended transfer with a subsequent attended transfer with the REDCOM LSC results in one-way audio. The vendor submitted a PoAM stating they will work with REDCOM to resolve the

JITC Memo, JTE, Extension of the Special Interoperability Test Certification of the Avaya CS2100 XA-Core SE09.1 –Aura™ AS5300 Version 2.0 Multifunction Softswitch (MFSS) (with specified patch releases) from Patch Bundle 18 to Patch Bundle 23

issue within 180 days. This was adjudicated by DISA to have a minor operational impact. Therefore, JITC approves this DTR. JITC's review of the DTR submission determined that there was no further impact on interoperability. Below is a synopsis of the multiple interoperability fixes included in Patch Bundles 19, 20, 21, 22, and 23:

Patch Bundle 19:

- RPM Security Update. Resolved in platform patch 13.0.30.
- Updated the server and windows JRE to release jre6u29. Resolved in Platform patch 13.0.30.
- IPsec causes kernel to crash. Resolved in Platform patch 13.0.30 .
- Failed attended transfers with the Cisco EBC. Resolved in SIP Core patch MCP_13.0.0.16_2011-11-25-0225.patch.
- Call Routing does not work. Resolved in SIP Core patch MCP_13.0.0.16_2011-11-25-0225.patch.
- The "o" line in the sdp answer is different from the "o" line in the sdp offer. Resolved in SIP Core patch MCP_13.0.0.16_2011-11-25-0225.patch.
- Add MSI installer file creation to build process on Hudson. Resolved in UC Client build 7.2.3076_20111108.

Patch Bundle 20

- Click2Call does not have means to add MKI to generated INVITES. Resolved in SIP Core patch MCP_13.0.0.17_2011-12-21-1321.patch.
- SIMRing on PA does not work correctly if call forward variants is also enabled. Resolved in SIP Core patch MCP_13.0.0.17_2011-12-21-1321.patch.
- Tomcat CVE-2011-3190 requires tomcat upversion. Resolved in SIP Core patch MCP_13.0.0.17_2011-12-21-1321.patch.
- Avaya CM6 cannot maintain session. Resolved in SIP Core patch MCP_13.0.0.17_2011-12-21-1321.patch.
- Element Manager History Log does not show large backup jobs. Resolved in MAS load 6.6.0.91.
- Call from Unistism CS1K user to UCC installed on Win7 OS works improperly. Resolved in UC Client build 7.2.3080_20111220.
- Call transfer for PCA users when announce transfer used is failed. Resolved in UC Client build 7.2.3080_20111220.

Patch Bundle 21

- Intermittent issue about TLS connection b/w MAS and PROV. Resolved in Platform patch 13.0.31.

JITC Memo, JTE, Extension of the Special Interoperability Test Certification of the Avaya CS2100 XA-Core SE09.1 –Aura™ AS5300 Version 2.0 Multifunction Softswitch (MFSS) (with specified patch releases) from Patch Bundle 18 to Patch Bundle 23

- Oracle Critical Patch Update January 2012. Resolved in Oracle Database patch 10.2.0.4.0 Patch Level: 25.
- 11xx is failed to retrieve service package. Resolved in SIP Core patch MCP_13.0.0.19_2012-02-29-0457.patch.
- AS5300 2.0: Prop US6914. Resolved in SIP Core patch MCP_13.0.0.19_2012-02-29-0457.patch.
- AS5300: 487 message is sent instead of 406. Resolved in SIP Core patch MCP_13.0.0.19_2012-02-29-0457.patch.
- SIMRing on PA does not work correctly if "call forward variants" is also enabled. Resolved in SIP Core patch MCP_13.0.0.19_2012-02-29-0457.patch.
- MeetMe Uninstall removing entire directory structure. Resolved in MAS load 6.6.0.92.
- EMS Server Install (Netra T5220): remove unneeded packages (Firefox, Thunderbird & Office). Resolved in AudioCodes EMS 5.8.94.
- EMS Server Install: Remove SUNWrcmdc package (DOD:JITC:GEN003865). Resolved in AudioCodes EMS 5.8.94.
- EMS Server: OpenSSL 0.9.8r is missing library link in /usr/lib. Resolved in AudioCodes EMS 5.8.94.
- EMS Server: 5.8.92 to 5.8.93 upgrade fails. Resolved in AudioCodes EMS 5.8.94.

Patch Bundle 22

- AS5300 2.0: Prop US6914. Resolved in SIP Core patch MCP_13.0.0.19_2012-02-29-0457.patch.
- AS5300 2.0 - Critical memory overload in SESM when making call to CS1K through direct SIP trunk. Resolved in SIP Core patch MCP_13.0.0.19_2012-02-29-0457.patch.
- When user calls with CS1K phone at the UC Client the call drops with internal error. Resolved in SIP Core patch MCP_13.0.0.19_2012-02-29-0457.patch.
- PB20 Install caused a JRE check servlet to fail to load. Resolved in SIP Core patch MCP_13.0.0.19_2012-02-29-0457.patch.
- MKI checkbox should be added in PA. Resolved in SIP Core patch MCP_13.0.0.19_2012-02-29-0457.patch.
- Users cannot be Deleted. Resolved in SIP Core patch MCP_13.0.0.19_2012-02-29-0457.patch.

Patch Bundle 23

- 11xx is failing to retrieve service package after being upgraded to new patch. This almost blocks SV testing. Resolved in SIP Core patch 13.0.0.20_2012-03-06-0225.patch

4. Table 1 lists the interface status of the SUT. Table 2 lists the Capability Requirements (CR) and Functional Requirements (FR), and component status of the SUT. The threshold CR and FR

JITC Memo, JTE, Extension of the Special Interoperability Test Certification of the Avaya CS2100 XA-Core SE09.1 –Aura™ AS5300 Version 2.0 Multifunction Softswitch (MFSS) (with specified patch releases) from Patch Bundle 18 to Patch Bundle 23

for LSCs are established by Sections 5.3.2, 5.3.4, 5.3.5, and 5.4 of Reference (d) and were used to evaluate the interoperability of the SUT.

Table 1. SUT Interface Interoperability Status

Interface	Critical	UCR Reference	Threshold CR/FR ¹	Status	Remarks ²
External Interfaces					
10Base-X	Yes	5.3.2.4.2	1, 2, 3, 4, 5, 6, 7, 9, 10, 11, 12, 13, and 14	Certified	Met threshold CRs/FRs for IEEE 802.3i and 802.3j for the AS-SIP trunk.
100Base-X	Yes	5.3.2.4.2	1, 2, 3, 4, 5, 6, 7, 9, 10, 11, 12, 13, and 14	Certified	Met threshold CRs/FRs for IEEE 802.3u for the AS-SIP trunk.
1000Base-X	Yes	5.3.2.4.2	1, 2, 3, 4, 5, 6, 7, 9, 10, 11, 12, 13, and 14	Certified	Met threshold CRs/FRs for IEEE 802.3z and 802.3ab. Applies to AS-SIP trunk interface.
ISDN T1 PRI ANSI T1.619a	Yes	5.3.2.4.3	2, 3, 6, 7, 9, 11, and 14	Certified	Met threshold CRs/FRs. This interface provides legacy DSN and TELEPORT connectivity.
ISDN T1 PRI NI-2	Yes	5.3.2.4.3	2, 3, 6, 7, 9, 11, and 14	Certified	Met threshold CRs/FRs. This interface provides PSTN connectivity.
E1 PRI ITU-T Q.931	No	5.3.2.12.10	2, 3, 6, 7, 9, 11, and 14	Certified	Met threshold CRs/FRs for this interface. This interface provides PSTN connectivity..
SONET OC-3	No	5.3.2.8.4	2, 3, 6, 7, 9, 11, and 14	Certified	Met threshold CRs/FRs for this interface.
NM					
10Base-X	Yes	5.3.2.4.4 5.3.2.7.2.8	15	Certified	Met threshold CRs/FRs for this interface. Verified via LoC.
100Base-X	Yes	5.3.2.4.4 5.3.2.7.2.8	15	Certified	Met threshold CRs/FRs for this interface. Verified via LoC.
NOTES:					
1. The SUT high-level CR and FR ID numbers depicted in the Threshold CRs/FRs column can be cross-referenced in Table 2. These high-level CR/FR requirements refer to a detailed list of requirements provided in Reference (c).					
2. Detailed information pertaining to open TDRs and associated operational impacts is in Reference (c).					
LEGEND:					
10Base-X	10 Mbps Ethernet		JITC	Joint Interoperability Test Command	
100Base-X	100 Mbps Ethernet		LoC	Letter of Compliance	
1000Base-X	1000 Mbps Ethernet		Mbps	Megabits per second	
802.3i	10 Mbps twisted pair media for 10Base-X networks		MLPP	Multi-Level Precedence and Preemption	
802.3j	10 Mbps fiber media for 10Base-X networks		NI-2	National ISDN Standard 2	
802.3u	100BASE-TX, 100BASE-T4, 100BASE-FX Fast Ethernet at 100 Mbps with auto negotiation		NM	Network Management	
ANSI	American National Standards Institute		OC-3	Optical Carrier Level 3 (155 Mbps)	
APL	Approved Products List		PRI	Primary Rate Interface	
AS-SIP	Assured Services Session Initiation Protocol		PSTN	Public Switched Telephone Network	
CAS	Channel Associated Signaling		Q.931	Signaling Standard for ISDN	
CCS7	Common Channel Signaling Number 7		Q.955.3	ISDN Signaling Standard for E1 MLPP	
CR	Capability Requirement		SONET	Synchronous Optical Network	
DSN	Defense Switched Network		SS	Softswitch	
E1	European Basic Multiplex Rate (2.048 Mbps)		SS7	Signaling System 7	
FR	Functional Requirement		SUT	System Under Test	
ID	Identification		T1	Digital Transmission Link Level 1 (1.544 Mbps)	
IEEE	Institute of Electrical and Electronics Engineers		T1.619a	SS7 and ISDN MLPP Signaling Standard for T1	
ISDN	Integrated Services Digital Network		TDR	Test Discrepancy Reports	
ITU-T	International Telecommunication Union – Telecommunication Standardization Sector		UC	Unified Capabilities	
			UCR	Unified Capabilities Requirements	
			WAN	Wide Area Network	

JITC Memo, JTE, Extension of the Special Interoperability Test Certification of the Avaya CS2100 XA-Core SE09.1 –Aura™ AS5300 Version 2.0 Multifunction Softswitch (MFSS) (with specified patch releases) from Patch Bundle 18 to Patch Bundle 23

Table 2. SUT CR and FR Status

CR/FR ID	Capability/Function	Applicability ¹	UCR Reference	Status	Remarks
1	Assured Services Product Features and Capabilities				
	DSCP Packet Marking	Required	5.3.2.2.1.4	Met	None
	Voice Features and Capabilities	Required	5.3.2.2.2.1	Partially Met ²	None
	Public Safety Features	Required	5.3.2.2.2.2	Met	None
	ASAC Voice	Required	5.3.2.2.2.3.1.2	Met	None
	ASAC Video	Required	5.3.2.2.2.3.2	Met	None
	Signaling Protocols	Required	5.3.2.2.2.3	Met	None
	Signaling Performance	Required	5.3.2.2.2.4	Met	None
2	Registration, Authentication, and Failover				
	Registration	Required	5.3.2.3.1	Met	None
	Failover	Required	5.3.2.3.2	Met	None
3	Product Physical, Quality, and Environmental Factors				
	Availability	Required	5.3.2.5.2.1	Met	None
	Maximum Downtimes	Required	5.3.2.5.2.2	Met	None
	Loss of Packets	Required	5.3.2.5.4	Met	None
4	Global Location Server				
	Global Location Server Requirements	Required	5.3.2.8.2.2	Met	None
5	LSC Requirements for WAN Softswitch				
	LSC Requirements	Conditional	5.3.2.7	Partially Met ³	None
6	Call Connection Agent Requirements				
	CCA IWF Component	Required	5.3.2.9.2.1	Met	None
	CCA MGC Component	Required	5.3.2.9.2.2	Met	None
	SG Component	Conditional	5.3.2.9.2.3	Not Tested ⁴	None
	CCA-IWF Support for AS-SIP	Required	5.3.2.9.5.1	Met	None
	CCA-IWF Support for SS7	Conditional	5.3.2.9.5.2	Not Tested ⁴	None
	CCA-IWF Support for PRI via MG	Required	5.3.2.9.5.3	Met	None
	CCA-IWF Support for CAS Trunks via MG	Conditional	5.3.2.9.5.4	Not Tested ⁴	None
	CCA-IWF Support for VoIP and TDM Protocol Interworking	Required	5.3.2.9.5.6	Met	None
	CCA Preservation of Call Ringing State during Failure Conditions	Required	5.3.2.9.6	Not Met ⁵	None
	CCA Interactions with Transport Interface Functions	Required	5.3.2.10.3	Met	None
	CCA Interactions with the EBC	Required	5.3.2.10.4	Met	None
	CCA Support for Admission Control	Required	5.3.2.10.5	Met	None
	CCA Support for UFS	Required	5.3.2.10.6	Met	None
	CCA Support for IA	Required	5.3.2.10.7	Met	None
	CCA Support for AS Voice and Video	Required	5.3.2.10.11	Partially Met ^{6,7}	None
CCA Interactions with Service control Functions	Required	5.3.2.10.12	Met	None	
CCA Interworking between AS-SIP and SS7	Conditional	5.3.2.11	Not Tested ⁴	None	

Table 2. SUT CR and FR Status (continued)

CR/FR ID	Capability/Function	Applicability ¹	UCR Reference	Status	Remarks
7	MG Requirements				
	Role of MG In SS	Required	5.3.2.12.3.2.1	Met	None
	MG Support for ASAC	Required	5.3.2.12.4.1	Met	None
	MG and IA Functions	Required	5.3.2.12.4.2	Met	None
	MG Interaction with Service Control Function	Required	5.3.2.12.4.3	Met	None
	MG Interactions with IP Transport Interface Functions	Required	5.3.2.12.4.4	Met	None
	MG-EBC interactions	Required	5.3.2.12.4.5	Met	None
	MG IP-Based PSTN Interface Requirements	Conditional	5.3.2.12.4.7	Not Tested ⁴	None.
	MG support for User Features and Services	Required	5.3.2.12.4.9	Met	None
	MG Interface to TDM	Required	5.3.2.12.5	Met ⁴	None
	MG Interface to TDM Allied and Coalition	Conditional	5.3.2.12.6	Not Tested ⁴	None.
	MG Interface to TDM PSTN in U.S	Required	5.3.2.12.7	Met	None
	MG Interfaces to TDM PSTN OCONUS	Required	5.3.2.12.8	Met	None
	MG Support for CCS7	Conditional	5.3.2.12.9	Not Tested ⁴	None
	MG Support for ISDN PRI Trunks	Required	5.3.2.12.10	Met	None
	MG Support for CAS Trunks	Conditional	5.3.2.12.11	Not Tested ⁴	None
	MG Echo Cancellation	Required	5.3.2.12.13	Met	None
MG Clock Timing	Required	5.3.2.12.14	Met	None	
MGC-MG CCA Functions	Required	5.3.2.12.15	Met	None	
MG V.150. ¹	Required	5.3.2.12.16	Not Met ⁸	None	
MG Preservation of Call Ringing during Failure	Required	5.3.2.12.17	Not Tested ⁵	None	
8	SG Requirements				
	SG and CCS7 Network Interactions	Conditional	5.3.2.13.5.1	Not Tested ⁴	None
	SG Interactions with CCA	Conditional	5.3.2.13.5.2	Not Tested ⁴	None
	SG Interworking Functions	Conditional	5.3.2.13.5.3	Not Tested ⁴	None
9	WWNDP Requirements				
	WWNDP	Required	5.3.2.16	Met	None
	DSN WWNDP	Required	5.3.2.16.1	Met	None
10	Commercial Cost Avoidance				
	Commercial Cost Avoidance	Required	5.3.2.23	Met ⁹	None
11	Precedence Call Diversion				
	Precedence call Diversion	Conditional	5.3.2.25	Met	None
12	AS-SIP Requirements				
	AS-SIP General Requirements	Required	5.3.4	Partially Met ⁷	None
	SIP Session Keep-Alive Timer	Required	5.3.4.8	Met	None
	Session Description Protocol	Required	5.3.4.9	Met	None
	Precedence and Preemption	Required	5.3.4.10	Met	None
	Video Telephony – General Rules	Required	5.3.4.12	Partially Met ⁷	None
	Calling Services	Required	5.3.4.13	Met	None
	SIP Translation Requirements for Inter-working AS-SIP Signaling Appliances	Required	5.3.4.14	Met	None
	Relevant Timers for the Terminating Gateway and the Originating Gateway	Required	5.3.4.15	Met	None
	SIP Requirements for Interworking AS-SIP Signaling Appliance	Required	5.3.4.16	Met	None
	Keep-Alive Timer Requirements for Interworking AS-SIP Signaling Appliances	Required	5.3.4.17	Met	None
Precedence and Preemption Extensions for Interworking AS-SIP Signaling Appliances	Required	5.3.4.18	Met	None	
Supplementary Services	Required	5.3.4.19	Met	None	
13	IPv6 Requirements				
	Product Requirements	Required	5.3.5.4	Partially Met ¹⁰	None

JITC Memo, JTE, Extension of the Special Interoperability Test Certification of the Avaya CS2100 XA-Core SE09.1 –Aura™ AS5300 Version 2.0 Multifunction Softswitch (MFSS) (with specified patch releases) from Patch Bundle 18 to Patch Bundle 23

Table 2. SUT CR and FR Status (continued)

CR/FR ID	Capability/Function	Applicability ¹	UCR Reference	Status	Remarks
14	Information Assurance				
	Information Assurance Requirements	Required	5.4	Met ¹¹	None
15	Network Management				
	General Management Requirements	Required	5.3.2.17.2	Partially Met ¹²	None
	VVoIP NMS Interface Requirements	Required	5.3.2.4.4	Partially Met ¹²	None
	Requirement for FCAPS Management	Required	5.3.2.17.3	Partially Met ^{12,13}	None
	NM requirements of Appliance Functions	Required	5.3.2.18	Partially Met ¹²	None
	Accounting Management	Required	5.3.2.19	Partially Met ¹²	None

NOTES:

1. The annotation of 'required' refers to a high-level requirement category. The applicability of each sub-requirement is provided in Reference (c).
2. The SUT had outstanding open TDRs at the completion of testing, which were adjudicated by DISA to have a minor operational impact. The vendor has submitted a POA&M to address the open TDRs. Reference (c) provides additional details. The DTR 18 request resulted in V&V testing conducted from 8 through 23 March 2012. During this test, a discrepancy was noted in which an unattended transfer with a subsequent attended transfer with the REDCOM LSC results in one-way audio. The vendor submitted a POA&M stating they will work with REDCOM to resolve the issue within 180 days. The one-way audio is cleared if the user puts the second "attended" transferred call on hold, then off hold, which results in two-way audio. This was adjudicated by DISA to have a minor operational impact.
3. The LSC is an optional integrated component of the SUT and; therefore, the SUT is certified for joint use with or without the LSC. The SUT was certified with noted minor operational discrepancies. The LSC Special Interoperability Certification letter and test summary report is posted on the UC APL under TN# 0911801. The SUT partially met PEI requirements (no video). The AEI and Operator Console requirements were not tested; this requirement represents a new UCR requirement (Jan 2010) at the time of the APL interoperability testing and therefore compliance is not mandatory at that time, based on allowance of an 18-month development cycle for new requirements.
4. This capability or interface is a conditional requirement for a WAN SS. The SUT met all the interfaces requirements for a T1 ISDN PRI (ANSI T1.619a and ANSI T1 607 NI2) and E1 ISDN PRI (ETSI PSTN interface only).
5. This requirement represents a new UCR requirement (Jan 2010) at the time of the APL interoperability testing and therefore compliance is not mandatory at that time, based on allowance of an 18-month development cycle for new requirements.
6. The SUT PEI hardphone met the UCR requirements for voice only. The PEI softphone met both voice and video requirements with one exception: The softphone can assign any DSCP value from 0-63 to media and signaling but cannot assign a unique DSCP value for each precedence level per the UCR when running on Windows Vista or Windows 7. The softphone assigns the same DSCP value for all precedence levels. This discrepancy was adjudicated by DISA on August 2011 with a minor operational impact.
7. The vendor did not support AEI video or voice capability. This was adjudicated by DISA to have a minor operational impact since there were no certified AEI video end instruments on the UC APL and furthermore, AEIs are a new UCR 2008, Change 1 requirement and therefore compliance is not mandatory at the time of APL interoperability testing, based on allowance of an 18-month development cycle for new requirements.
8. The vendor did not demonstrate V.150.1 support. This requirement represents a new UCR requirement (Jan 2010) at the time of the APL interoperability testing and therefore compliance is not mandatory at that time, based on allowance of an 18-month development cycle for new requirements.
9. The SUT met this requirement with a Lightweight Directory Access Protocol server which is covered under a separate Interoperability Certification listed separately on the UC APL.
10. The DISA adjudicated all open TDRs to have a minor operational impact. The fielding of the SUT is limited to IPv4 across the DISN based on the fielding environment, IPv6 partial compliance and POA&M addressing critical IPv6 discrepancies in their next major release in 2012. DISA retains the authority to remove this product from the Department of Defense (DoD) Unified Capabilities (UC) Approved Products List (APL) as follow-on products are fielded with full IPv6 capability. The SUT was tested and met IPv6 interoperability requirements with its optional LSC intra-enclave only with the following discrepancies which were adjudicated by DISA as having a minor operational impact:
 - a. POA&M. The SUT does not meet RFC 4007 for IPv6 Scoped Address Architecture.
 - b. The SUT does not support IPv6 (Signaling or Media) with the MP112 and MP124 analog IADs.
 - c. The SUT SESM Core supports IPv4 only for signaling inter-enclave (WAN).
 - d. The SUT Audio Codes MG3K supports IPv4 only for signaling and both IPv4 and IPv6 dual stack for media intra and interenclave.
11. Information Assurance was tested by a DISA-led Information Assurance test team and published in a separate report, Reference (f).

JITC Memo, JTE, Extension of the Special Interoperability Test Certification of the Avaya CS2100 XA-Core SE09.1 –Aura™ AS5300 Version 2.0 Multifunction Softswitch (MFSS) (with specified patch releases) from Patch Bundle 18 to Patch Bundle 23

Table 2. SUT CR and FR Status (continued)

NOTES (continued):			
12. The vendor submitted a NM LoC with noted discrepancies. The following open TDRs were adjudicated by DISA to have a minor operational impact with a vendor submitted POA&M:			
a. The SUT does not fully support SNMP and MIBs IAW IETF Standards 58 and 62.			
b. The SUT is not fully compliant with NM call detail records formats.			
c. SUT does not support management requirements for ASAC.			
13. The SUT does not support destination code controls. The SUT does not have the capability of setting the percentage of calls to be blocked to the designated destination(s). This was adjudicated by DISA to have a minor operational impact.			
LEGEND:			
AEI	Assured Services End Instrument	LSC	Local Session Controller
APL	Approved Products List	Mbps	Megabits per second
ASAC	Assured Services Admission Control	MG	Media Gateway
AS	Assured Services	MGC	Media Gateway Controller
ASD/NII	Assistant Secretary of Defense for Networks and Information Integration	MIB	Management Information Base
AS-SIP	Assured Services Session Initiation Protocol	NM	Network Management
CAS	Channel Associated Signaling	NMS	Network Management System
CCA	Call Connection Agent	OCONUS	Outside the Continental United States
CCS7	Common Channel Signaling Number 7	PEI	Proprietary End Instrument
CR	Capability Requirement	POA&M	Plan of Action and Milestones
CM	Configuration Management	PRI	Primary Rate Interface
DISA	Defense Information Systems Agency	PSTN	Public Switched Telephone Network
DISN	Defense Information System Network	RFC	Request for Comment
DoD	Department of Defense	SESM	Subscriber Edge Services Manager
DSCP	Differentiated Services Code Point	SG	Signaling Gateway
DSN	Defense Switched Network	SIP	Session Initiation Protocol
E1	European Basic Multiplex Rate (2.048 Mbps)	SNMP	Simple Network Management Protocol
EMS	Element Management System	SNMPv2	Simple Network Management Protocol version 2
FR	Functional Requirement	SNMPv3	Simple Network Management Protocol version 3
IA	Information Assurance	SS	Softswitch
IAW	In accordance with	SS7	Signaling System 7
IETF	Internet Engineering Task Force	SUT	System Under Test
IP	Internet Protocol	T1	Digital Transmission Link Level 1 (1.544 Mbps)
IPSec	Internet Protocol Security	TDR	Test Discrepancy Report
IPv6	Internet Protocol version 6	TDM	Time Division Multiplexing
ISDN	Integrated Services Digital Network	UC	Unified Capabilities
IWF	Interworking Function	UCR	Unified Capabilities Requirements
LDAP	Lightweight Directory Access Protocol	VoIP	Voice over Internet Protocol
LoC	Letter of Compliance	VVoIP	Voice and Video over Internet Protocol
		WAN	Wide Area Network
		WWNDP	World Wide Numbering and Dialing Plan

5. No detailed test report was developed in accordance with the Program Manager’s request. JITC distributes interoperability information via the JITC Electronic Report Distribution (ERD) system, which uses Unclassified-But-Sensitive Internet Protocol Router Network (NIPRNet) e-mail. More comprehensive interoperability status information is available via the JITC System Tracking Program (STP). The STP is accessible by .mil/gov users on the NIPRNet at <https://stp.fhu.disa.mil>. Test reports, lessons learned, and related testing documents and references are on the JITC Joint Interoperability Tool (JIT) at <http://jit.fhu.disa.mil> (NIPRNet). Information related to DSN testing is on the Telecom Switched Services Interoperability (TSSI) website at <http://jitc.fhu.disa.mil/tssi>. Due to the sensitivity of the information, the Information Assurance Accreditation Package (IAAP) that contains the approved configuration and deployment guide must be requested directly through government civilian or uniformed military personnel from the Unified Capabilities Certification Office (UCCO), e-mail: ucco@disa.mil.

JITC Memo, JTE, Extension of the Special Interoperability Test Certification of the Avaya CS2100 XA-Core SE09.1 –Aura™ AS5300 Version 2.0 Multifunction Softswitch (MFSS) (with specified patch releases) from Patch Bundle 18 to Patch Bundle 23

6. The JITC point of contact is Capt Stephane Arsenault, JITC, commercial (520) 538-5269 or DSN 312-879-5269; e-mail address is Stephane.Arsenault@disa.mil. The JITC's mailing address is P.O. Box 12798, Fort Huachuca, AZ 85670-2798. The UCCO tracking number is 0903501.

FOR THE COMMANDER:

Enclosure a/s


for BRADLEY A. CLARK
Chief
Battlespace Communications Portfolio

Distribution (electronic mail):

Joint Staff J-6

Joint Interoperability Test Command, Liaison, TE3/JT1

Office of Chief of Naval Operations, CNO N6F2

Headquarters U.S. Air Force, Office of Warfighting Integration & CIO, AF/XCIN (A6N)

Department of the Army, Office of the Secretary of the Army, DA-OSA CIO/G-6 ASA (ALT), SAIS-IOQ

U.S. Marine Corps MARCORSSYSCOM, SIAT, MJI Division I

DOT&E, Net-Centric Systems and Naval Warfare

U.S. Coast Guard, CG-64

Defense Intelligence Agency

National Security Agency, DT

Defense Information Systems Agency, TEMC

Office of Assistant Secretary of Defense (NII)/DOD CIO

U.S. Joint Forces Command, Net-Centric Integration, Communication, and Capabilities Division, J68

Defense Information Systems Agency, GS23

ADDITIONAL REFERENCES

- (c) Joint Interoperability Test Command, Memo, JTE, "Special Interoperability Test Certification of the Avaya CS2100 XA-Core SE09.1 –Aura™ AS5300 Version 2.0 Multifunction Softswitch (MFSS) (with specified patch releases)," 29 December 2010
- (d) Office of the Assistant Secretary of Defense, "Department of Defense Unified Capabilities Requirements 2008, Change 1," 22 January 2010
- (e) Joint Interoperability Test Command, "Unified Capabilities Test Plan (UCTP)," Draft
- (f) Joint Interoperability Test Command, "Information Assurance (IA) Assessment of Avaya Aura™ CS2100 XA-Core SE09.1 w/AS5300 Version 2.0 MFSS (TN 0903501)," 25 March 2011